104209 Work Order ID 104209 Page 1 July-09-13 11:42:18 AM Accept *N900040100* Setup Start Item ID: D4034-043 **Revision ID:** Fwd Upper Rib Assembly Item Name: *4* 7/09/13 Start Qty: 4.00 **Cust Item ID: Start Date:** Required Date: 7/09/13 Req'd Qty: 4.00 **Customer:** Reference: Run Date: 13-57-12 Tooling: Date: Process Plan: MUT **Approvals:** Stop Date: SPC (Y/N): Date: **Tool ID** Tool # Plan Accept Reject Reject Insp. Operation Set Up/ Sequence ID/ **Qty Qty** Number Stamp Work Center ID Description Code **Run Hours** Draw Nbr **Revision Nbr** C D4034 Weld per dwg A/R S.S. rod Batch: 123823 0.00 100 CC 13-9-18 *100* 0.00 Large Fab Memo Large Fab 1- Assemble ribs to hoop and weld as per dwg DT9564 2- Weld bushing in rib as per dwg QC9- Inspect visual per QSI004- Fusion Welds 110 0.00 *110* 0.00 QC Memo Quality Control 120 QC5- Inspect part completeness to step on W/O 0.00 *120*

0.00

Memo

Quality Control

DQA:		_ Date:	<u></u>		- ΛΛDŤ											
QA Closed:		Date:		WORK OR	WORK ORDER NON-CONFORMANCE / UPDATE Work Order update only											
QA Closed.		Date.			Work Order appeare only											
Work Orde	r:			DISPOS	SITION		AGAINST DEPARTMENT/PROCESS									
				-	Rework		Skid-tube	Crosstube	7	Water Jet	Engineering	I				
Part N	0.				Scrap		Machining	Small Fab	Pro	Quality						
				_	Use-as-is		noforming	Finishing	→	re/Packaging						
NCR N	0			Suspected Una	pproved		Large Fab	Composite]	Supplier						
		1								,						
Root			1 1	Description of work or	· ·	Initial		tion	Sign &							
Cause	Date	Step	Qty	or non-conform	iance (Chief Eng	Descr	ription	Date	Verification	QC Inspector	_				
Design	_							4								
Doc/Data																
Equip/Tooling	_															
Handling/Pre																
Material	_															
Operator																
Offset/Setup																
Process																
Supplier Training	-															
Transport																
Unapproved																
	<u> </u>	1			F	AULT CA	TEGORY					_				
Landin	g Gear			General												
, [Bending		.09	Bend	Γ	Folio/F	rogram	Г	Outside Dim	ensions	Pressure/Forced					
Ī	Centre N	ot Concer	ntric	BOM/Route		Grain	J	. [Over/Under	}	Set-up					
	Cracks			Broken/Damage	/Defect	Hardwa	ire		Part Incorred	it -	Temperature/Cure	!				
	Crimp/Ki	nk/Ripple	/Wave	Burrs		Inspect	ion Incomplete/Ur	nqualified	Part Lost/Mi	ssing	Weld					
[Cuffs			Contamination		Instruct	ions Incomplete/L	Jnclear	Part Moved		Wrong Stock Pulled	d				
	Crushing			Countersink		Misalig	ned/off center		Positioned V	√rong						
	Heat Trea	at		Cut Too Short		Mislabe	eled		Power Loss/	Surge	Other					
	Inspectio	n Štrip in	Tube	Drawing		Misread	t									
	Marks/Cl	natter		Drill Holes		Off-set										
	Turning S	equence		Finish		Out of 0	Calibration									
	Wave/Tw	vist in Tub	oe	Fit/Function		Out of Sequence										

Work Ord <i>July-09-13 11:4</i>		4209		*104209*								Page 2
Item ID: D4034-043 Revision ID:				Accept	*N900)*	Setup St		*NS1*			
Item Name:	Fwd Upper Ri	b Assembly							S	top :	*N:	32 *
Start Date: 7/09/13 Start Qty: 4.00 Required Date: 7/09/13 Req'd Qty: 4.00			*4* *4*		Cust Item I Customer:							
Reference:	,		•						- C	44	_	
Approvals: Process Plan:QC:		ın:	Date:	Tooling: SPC (Y/N):	Da			tart :	*NR1* *NR2*			
Sequence ID/ Work Center II	D	Operation Description Identify as per dwg & St	4	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accep Qty	Qty	Nu	ject mber	Insp. Stamp
120 Packaging Packaging		Memo	604	0.00				CC	<u> 13-</u>	9-ZC)	
140		QC21- Final Inspection	- Work Order Release	0.00		/						
140 QC Quality Control		Мето		0.00		V		W	_5	137 M	09-7	13-09

DQA:			Date: _.			WORK ORDER NON-CONFORMANCE / UPDATE Work Order update only										
QA Closed:		i	Date:													
Work Order:						DISPOSITION										
Part No.						Rework Scrap			Skid-tube Machining		Water let Prod. Eng. Coor. Rec/Store/Packaging			Engineering Quality Other		
NCR N	No					Use-as-is Suspected Unapproved		mern	noforming Large Fab	Finishing Composite	~—	, Rec/Stor	Other			
Root					Desci	ription of work order update		Initial	А	ction		Sign &	<u> </u>			
Cause	Dat	e :	Step	Qty		or non-conformance	Ch	nief Eng	Des	scription		Date	Verificatio	n QC Inspector		
Design Doc/Data																
Equip/Tooling	\square															
Handling/Pre																
Material																
Operator																
Offset/Setup																
Process																
Supplier		İ														
Training	-															
Transport																
Unapproved																
							FA	ULT CAT	EGORY					1		
Landir	ng Gear				•	General					•					
	Bending Centre Not Concentric Cracks Crimp/Kink/Ripple/Wave					Bend		Folio/P	rogram			Outside Dim	ensions	П	Pressure/Forced	
						BOM/Route		Grain				Over/Under	tolerance	П	Set-up	
						Broken/Damage/Defect		Hardwa	re	•		Part Incorred	:t		Temperature/Cure	
						Burrs		Inspecti	on Incomplete/	Unqualified		Part Lost/Mi	ssing		Weld	
	Cuffs					Contamination		Instruct	ions Incomplete	e/Unclear		Part Moved			Wrong Stock Pulled	
	Crush	ing				Countersink		Misalig	ned/off center	r		Positioned V	/rong			
	Heat	Γreat				Cut Too Short		Mislabe	led			Power Loss/:	Surge		Other	
	Insped	ction Si	trip in	Tube		Drawing		Misread	1.							
	Marks	/Chatt	er	, ,		Drill Holes		Off-set		-						
	Turnir	ng Sequ	uence			Finish		Out of 0	Calibration							
[Wave/Twist in Tube					Fit/Function		Out of s	Convence							

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH

July-09-13 11:42:17 AM

Work Order ID:

104209

Parent Item:

D4034-043

Parent Item Name:

Fwd Upper Rib Assembly

Start Date: 7/09/13

Required Date: 7/09/13

Start Qty: 4.00

Required Qty: 4.00

Comments:

IPP RevA: new issue DD 09.11.23 verified by:EC

IPP Rev:B as per dwg revA 10.03.15

IPP Rev:C 11.01.19 AS PER DWG REV.B DD VERF:EC Rev:D 13.03.14 AS PER DWG REV.pc1 DD VERF:JLM IPP REV:E 13.06.21 DWG REV.C

7

12

DD VEDE-IES

verified by:EC

Component Item ID/	Replacement	Mfg/	Bin	Primary	Last	Route	Unit of	Qty on	Qty per Kit	Total	Qty	Date	Status
Item Name	Item ID	Purch	Item	Location	Location	Seq ID	Measure	Hand		Qty	Issued	Issued	
D4021-7		Manufactured	No			100	Each	5.0000	1	4	CC 1.	2-9-1	 1 B
Ноор									-		<u> </u>	<u> </u>	<u>o</u>
				Location		Loc Qty		oc Code	- /	3			
X				WA004		5	B103:	582 -		<u>3x)</u>			
				100	432	2	B1058	7/2 7		<u> </u>			
(884	28			787 —		<u></u>			
D4021-9		Manufactured	No			100	Each	327.0000	4	16	CC	17-9	7-10
Bushing												15 /	10
				Location		Loc Qty	<u>L</u> c	oc Code					
				WA		36							
				103	746	36							
				WA002		6					, es		
				102	482	4					,		
				991	43	2							
				WA004		285							
					402	55				200			" 2.
					917	40			_(ZOX			
					2664	80							
					3548	50							
				664 703		2							
		,		703 724		4					••		
				829]							
				847		3							
				880		23							

88377

92020 98877

DQA:	A: Date:												**			
						WORK ORDER NON-CONFORMANCE / UPDATE										
QA Closed:			Date:			Work Order update only										
Work Orde	er:					DISPOSITION										
						Rework		Skid-tube			Water Jet	Engineering				
Part N	lo.					Scrap			Machining	Crosstube Small Fab		Prod. Eng. Coor.			Quality	
						Use-as-is			noforming	Finishing		Rec/Store/Packaging			Other	
NCR N	۱o					Suspected Unapproved			Large Fab	Composite						
													· ·			
Root					Desci	ription of work order update	1	Initial	Act	ion		Sign &				
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Descr	iption		Date	Verification	_	QC Inspector	
Design	_															
Doc/Data	_															
Equip/Tooling																
Handling/Pre	4															
Material																
Operator	_															
Offset/Setup																
Process	_					·										
Supplier	-															
Training	\dashv		-													
Transport	\dashv															
Unapproved			<u> </u>	<u> </u>			EAL	III CAT	I TEGORY			<u> </u>	<u> </u>			
Landir	on Go		· · · · · · · · · · · · · · · · · · ·			General	FA	OLI CA	EGORT						·	
Landii		ending			•	Bend		leolio/B	rogram		Γ_	Outside Dim	onsions T	٦,	Pressure/Forced	
			ot Concer	ntric		BOM/Route	\vdash	Grain	rogram		H	Over/Under	⊢	_	Set-up	
	_	racks	or comeer	16116		Broken/Damage/Defect		Hardwa	Ire			Part Incorre	⊢	-	Temperature/Cure	
			ık/Ripple	/Wave		Burrs	\vdash	4	ion Incomplete/Un	ngualified		Part Lost/M	 	_	Weld	
	_	uffs	,, -, -,	,		Contamination		1	ions Incomplete/U	`		Part Moved	-	_	Wrong Stock Pulled	
	_	rushing				Countersink	Н	4	ned/off center			Positioned V	∟ Vrong	╜`	2 2000 4 4 4	
	\blacksquare	leat Trea	t			Cut Too Short	$\overline{}$	Mislabe			_	Power Loss/	_	\neg	Other	
ľ			n Strip in	Tube		Drawing	-	Misread					~ <u>_</u>			
ľ		⁄Iarks/Ch				Drill Holes	\vdash	Off-set								
	Пт	urning S	equence			Finish	_	1	Calibration							
	V	Vave/Tw	ist in Tub	e		Fit/Function		Out of S	Sequence							

H:/FORMS/Quality Assurance\approved QA/NCRWO RevH

July-09-13 11:42:18 AM

Work Order ID: 104209 Required Date: 7/09/13 **Start Date:** 7/09/13 Parent Item: D4034-043 Start Qty: 4.00 Required Qty: 4.00 Fwd Upper Rib Assembly Parent Item Name: 8.0000 100 Each No CC 13-9-18 D4034-1 Manufactured Rib Loc Qty Location WA004 101056 83755 89359 97591 100 Each 11.0000 Manufactured No D4034-3 Rib Loc Qty Loc Code Location WA 101013 WA004 101014 WA005 2 94179

DQA:			Date:											\square \triangle \triangle \triangle \triangle	,	
QA Closed:			Date:			WORK ORDER NON-CONFORMANCE / UPDATE Work Order update only										
QA Closed.			Date.							·	work Order t	ipuate offiy			-	
Work Ord	er:					DISPOSITION										
	-					Rework]		Skid-tube	Crosstube		Water Jet		Engineering		
Part f	No.					Scrap			Machining	Small Fab	Pr	od. Eng. Coor.	Quality	,		
						Use-as-is		Thern	noforming	Finishing	 1	ore/Packaging		Other		
NCR I	No					Suspected Unapproved]		Large Fab	Composite		Supplier				
Root					Desc	ription of work order update	_	Initial	Acti	ion	Sign &	1			_	
Cause		Date	Step	Qty	·	or non-conformance	1	nief Eng	Descr		Date	Verificatio	n	QC Inspector		
Design			Jiep	Ψι,		or non comormance	<u> </u>	iici, ciig	<i>D</i> esc.	TPCION .	Date	Vermeatio	11	QC IIISPECTOI	_	
Doc/Data	П															
Equip/Tooling	П															
Handling/Pre	П															
Material	П															
Operator	П															
Offset/Setup																
Process																
Supplier																
Training																
Transport																
Unapproved																
							FA	ULT CAT	ΓEGORY						_	
Landi	ng G	ear				General		_		_						
	Ш	Bending				Bend		Folio/P	rogram	·	Outside Dir	mensions		Pressure/Forced		
	∐'	Centre No	ot Concen	ntric		BOM/Route		Grain			Over/Unde	r tolerance		Set-up		
	\vdash	Cracks				Broken/Damage/Defect		Hardwa	ire		Part Incorre	ect		Temperature/Cure		
	Цʻ	Crimp/Kir	nk/Ripple,	/Wave		Burrs		Inspecti	ion Incomplete/Un	qualified	Part Lost/N	1issing		Weld		
	-	Cuffs				Contamination		Instruct	ions Incomplete/U	Inclear	Part Moved	i		Wrong Stock Pulled		
	Н	Crushing				Countersink		Misalig	ned/off center		Positioned	Wrong				
	\vdash	Heat Trea				Cut Too Short		Mislabe	eled		Power Loss	/Surge		Other	_	
		Inspection		Tube	<u></u>	Drawing		Misread	t						_	
	_	Marks/Ch				Drill Holes		Off-set							_	
	$\overline{}$	Turning S	-			Finish	L	1	Calibration						_	
	Wave/Twist in Tube					Fit/Function	1	Dut of S	Seguence							







